

FIELD ENGINEERING CORRESPONDENCE

DATE:

December 12, 1974

TO:

All Depot Personnel

·C·

R. Parent

W. Grove

FROM:

R. Boynton

D. Larson

SUBJECT:

Depot Procedure

The following is in reference to which relates to problems that Graphic Systems 1210 frames have exhibited at site and cannot be reproduced at the depot. Some insight into this problem has shown, that Graphic Systems has turn-key consoles which are wired to start their program as soon as power is turned on. This means that RUN should be inhibited until +5 OK and mem OK are true. In some 1210 power supplies +5 OK is coming true before it should (the reason for the DIB) and causing Graphic System to express "cannot load program or "cold start problem" on their Discrepancy Report. It is imperative that all 1210 frames from Graphic Systems have the change (DIB #9) installed before being shipped.

Thank you in advance for your cooperation.

RICHARD BOYNTON

Redand 17 Graph

RB/ds



DEPOT INFORMATION BULLETIN

Field Service

Subject:

1210 Cold Start Problems.

There have been several 1210 frames returned to Westboro with "cold start" problems. The way to check out the frames is to load a memory with Exerciser. Then placing memory in suspect frame, hold start switch up and turn on the machine. The program, if a cold start problem exists, will halt.

The problem can be fixed by replacing R14, (1K res) with a 1.1K resistor. R14 is located next to U1, between U1 and U2. R14 can be easily replaced by removing the 20,000 MFD cap that covers U1.

To test the frame, follow the check out procedure with the frame cold. With start switch up and power applied, the machine should go into run and start the program.

Submitted by: J. COSTELLO - WESTBORO	Date: 12/12/74
Reviewed by: Reclara Brepain	Date: 12/12/24