


Address	B	16.	
237	217	4.63	
433	413		
437	417	14.99	VIMH =
625	605		14.82 C
630	610		
1034	1014		
		237	

6	7	8	9	0	1	2	3	4	5
				0	0	1	1	1	1
				1	0				



063077-

- AC3 71
- AC3 20.00 =
- AC3 222
- AC3 23.00
- AC3 230
- AC3 25.00
- 231
- 36.00
- 40. DYLE
- 234

AC3 = 37  
AC3 = 71

ADDR	YXXO					YOX			XXO				OX		
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
1760			0	0	1	1	1	1	1	1	1	0	0	0	0
DRIVE LINE Ic#			0			7			16				0		
2760					1	0	1	1	1	1	1	0	0	0	0
					1	3			16				0		
5760			1	0	1	1	1	1	1	1	1	0	0	0	0
			2			7			16				0		
6760			1	1	1	0	1	1	1	1	1	0	0	0	0
			3			3			16				0		
0560			0	0	0	1	0	1	1	1	1	0	0	0	0
			0			2			16				0		
1360			0	0	1	1	0	1	1	1	0	0	0	0	0
			0			6			16				0		
3200		1	0	1	1	0	1	0	0	0	0	0	0	0	0
			5			5			0				0		
237						1	0	0	1	1	1	1	1	1	1
						0	0	1	0	3			7		
433						1	0	0	0	1	1	0	1	1	1
						0	2	0	0	1			0		
437						1	0	0	0	1	1	1	1	1	1
						0	2	0	0	3			7		
625						1	1	0	0	1	0	1	0	1	1
4000						0	3	0	2				5		
6000			0	0	1	0									
6000			0	0	1	0	0	0	0	0	0	0	0	0	0
			0	0	1	0									

DRIVE LINE	=	<sup>1200</sup> 16K	=	Area # 16K
X00,02	=	U46	=	U49
X01,03	=	U47	=	U50
X04,06	=	U51	=	U54
X05,07	=	U52	=	U55
X00,010	=	U43	=	U46
X020,030	=	U42	=	U45
X040,050	=	U41	=	U44
X060,070	=	U40	=	U43
X100,110	=	U34	=	U37
X120,130	=	U33	=	U36
X140,150	=	U32	=	U35
X160,170	=	U29	=	U32
Y00,04	=	U70	=	U73
Y01,05	=	U69	=	U72
Y02,06	=	U67	=	U70
Y03,07	=	U66	=	U69
Y000,020	=	U65	=	U68
Y010,030	=	U64	=	U67
Y040,060	=	U63	=	U66
Y050,070	=	U62	=	U65
Y100,120	=	U60	=	U63
Y110,130	=	U59	=	U62
Y140,160	=	U58	=	U61
Y150,170	=	U57	=	U60

1. TELETYPE OUTPUT

0	060477	READS	Start @ location 0
1	061111	DOAS, 0	Set the lower 8 data
2	063611	SKPDN	switches to the bits
3	000777	JMP.-1	you desire to output.
4	000000	JMP 0	Allows scoping output

2. TELETYPE IN/PUT

0	060110	NIO,S	Start @ location 0
1	063610	SKPDN	reads any paper tape,
2	000777	JMP.-1	continually, into AC <sup>3</sup> -
3	074510	DIAS,3	Allows scoping input
4	063610	SKPDN	circuits.
5	000777	JMP.-1	
6	000001	Jmp 1	

3. ECHO KEYBOARD

0	063610	SKPDN	Starts @ location 0
1	000777	JMP.-1	Character typed on
2	060610	DIAC,0	keyboard should be
3	063710	SKPDZ	printed on printer
4	000777	JMP.-1	keyboard → CPU → Printer
5	061111	DOAS,0	
6	000000	JMP 0	

4. ECHO TAPE #1

0	060110	NIO,S	Start @ location 0
1	063610	SKPDN	The tape read
2	000777	JMP-1	is printed on
3	060610	DIAC,0	the printer.
4	063510	SKPBZ	
5	000777	JMP-1	
6	061111	DOAS,0	
7	063611	SKPDN	
10	000777	JMP-1	
11	000000	JMP 0	

5. ECHO TAPE #2

0	060110		Ditto #4
1	063610		
2	000777		
3	060510		
4	063511		
5	000777		
6	061111		
7	000001		

DIB

#94

*Zell*

211

*Jerry*

DEPOT INFORMATION BULLETIN

Field Service

Subject: TROUBLESHOOTING AID FOR NOVA LINE MEMORIES:

This DIB will check for any drivers which would hold down the read and write source voltages on all Nova line Memories.

The 3 watt current resistors on the memories should not have any noticeable voltage drop across them. If there is a voltage drop, then you have a bad driver or drivers which are holding the voltage down. The solution to this problem is to cut Pin 11 on the drivers, until the voltage drop across the current resistor is approximately 0 volts. Usually the first and fourth drivers of the group which pertain to that particular current resistor should be cut first. These measurements should be made with a DVM under static conditions.

*Copy every F.B.*

Submitted by:	Russell Carreiro <i>RPC</i>	Date:	10/5/77
Reviewed by:	Jack Nadon <i>AN</i>	Date:	10/5/77



FIELD ENGINEERING SUPPORT SOUTHBORO

*Technical Information Bulletin*

**TIB**

DATE: 19 APRIL 1974  
FROM: R. JENSEN  
SUBJECT: MISSING CAPACITOR

NUMBER: S1005  
CATEGORY: MEMORIES  
MODEL: 8300, 8301, 8302,  
AND 8117

---

On the 1200 16K Memory and all Nova II Memories (4K, 8K, and 16K), a de-coupling capacitor for -5 volts has inadvertently never been installed. It is strongly recommended that this capacitor be installed when encountering any of these memories.

Symptoms:

When running a Memory Test, turning the Teletype off/on causes a Memory failure. Secondary method is a visual inspection. Holding board by connector, look for a 6.8 MF 35V cap between -5 volt etch and ground. To the right of the sense amp for bit 14 and 15 is a crosshatch of etches. This is the ground connection for the cap. One of the etches between this crosshatch and the sense amp is -5 volts. This varies with each memory and also with Rev. level so more precise instructions cannot be given. (See ECO 2507 for precise location.)

Solution:

Install 6.8 ufd 35 tant capacitor (DG Part No. 103-000-002) to right of sense amp for bits 14 and 15 between -5 volts etch and ground etch. Use existing feedthru holes. ECO 2507 is generated to correct this problem.

Thanks to Parker Sutherland of the New England Depot for finding this problem and bringing this to attention.



FIELD ENGINEERING SUPPORT SOUTHBORO

*Technical Information Bulletin*

**TIB**

DATE: FEBRUARY 19, 1975  
FROM: D. REED  
SUBJECT: VOLTAGE REGULATOR & THRESHHOLD  
POTENTIOMETER ADJUSTMENTS FOR  
8117 MEMORIES WITH ECO 2565  
INSTALLED

NUMBER: S1008  
CATEGORY: MEMORIES  
MODEL: 8117

---

All 8117 16K Memories, Artwork 107-000-185-03 and above, with ECO 2565 installed should have R5 & R198 adjusted as follows:

Voltage Regulator Pot (R5) fully clockwise  
Threshold Pot (R198) fully counterclockwise

Rev 02 and below, or REV 03 and higher without ECO 2565, should not be field adjusted due to the fact that an adjustable voltage supply is required for +VINH.

The best means of ascertaining if ECO 2565 has been implemented is as follows:

- (1) R73 510 OHM  $\frac{1}{2}$  resistor deleted.
- (2) C19, C36, C42, C52, C57, C68, C71, C84  
100pf capacitors changed to 220pf.
- (3) R43, R80, R111, R114, R151, R155, R190, R199  
3300 OHM resistors deleted.

See TIB S1007 - Category: MEMORIES



FIELD ENGINEERING SUPPORT SOUTHBORO

*Technical Information Bulletin***TIB**

DATE: 29 OCTOBER 1974  
FROM: D. REED  
SUBJECT: FIELD INSTALLATION OF ECO 2565

NUMBER: S1007  
CATEGORY: MEMORIES  
MODEL: 8117

---

ECO 2565 balances the Read/Write currents of the 8117 16 K memories to allow them to pass Multiprogramming test. This ECO is implemented by changing the values of ten components for Rev. 3 & 4 and eighteen components for Rev. 5 and above. Eight of these components are capacitors and resistors which are varied at test level to achieve optimum memory margins. Since the selection of these components requires special test equipment, it is not recommended that this change be attempted in the field. 8117 memories which require this change may be returned to a repair depot for updating per Data General Corporation standard repair procedures.



DATE: 19 APRIL 1974  
FROM: R. JENSEN  
SUBJECT: MISSING CAPACITOR

NUMBER: S1005  
CATEGORY: MEMORIES  
MODEL: 8300, 8301, 8302  
AND 8117

---

On the 1200 16K Memory and all Nova II Memories (4K, 8K, and 16K), a de-coupling capacitor for -5 volts has inadvertently never been installed. It is strongly recommended that this capacitor be installed when encountering any of these memories.

**Symptoms:**

When running a Memory Test, turning the Teletype off/on causes a Memory failure. Secondary method is a visual inspection. Holding board by connector, look for a 6.8 MF 35V cap between -5 volt etch and ground. To the right of the sense amp for bit 14 and 15 is a crosshatch of etches. This is the ground connection for the cap. One of the etches between this crosshatch and the sense amp is -5 volts. This varies with each memory and also with Rev. level so more precise instructions cannot be given. (See ECO 2507 for precise location.)

**Solution:**

Install 6.8 ufd 35 tant capacitor (DG Part No. 103-000-002) to right of sense amp for bits 14 and 15 between -5 volts etch and ground etch. Use existing feedthru holes. ECO 2507 is generated to correct this problem.

Thanks to Parker Sutherland of the New England Depot for finding this problem and bringing this to attention.





