DATE:	3 AUGUST 1973	**NUMBER:**	S1005
FROM:	AUSTIN BELANGER	**CATEGORY:**	PROCESSORS
SUBJECT:	ABSENCE OF ECO 1325 ON 1200 CPU	**MODEL:**	1200,1210,1220

NOISE ON $\overline{\text{DCHR}}$ AND $\overline{\text{INTR}}$ MAY PUT COMPUTER INTO ILLEGAL STUTTER STATE; THIS CAUSES A SYMPTOM MUCH LIKE AN INFINITE DEFER LOOP IN THAT THE SYSTEM CAN BE HALTED ONLY BY RESET.

ECO 1325 SOLVES THIS PROBLEM BY LATCHING $\overline{\text{DCHR}}$ SO THAT ANY NOISE ON $\overline{\text{DCHR}}$ CANNOT RESET DCHA.

THIS ECO IS A CLASS 3 AND THEREFORE WAS NOT SENT TO THE FIELD. IF YOU ENCOUNTER THIS PROBLEM, CONTACT FIELD SERVICE, SOUTHBORO, FOR A COPY OF THE ECO.