IRIS
CUSTOMER
SUPPORT
BULLETIN

January 10, 1985

POINT 4 Data Corporation

```
                                        4444    4
                                        4444     444
                                        444    4  4444
                                        4   444  4444

                                        4444444  4444
                                        444444   444
                                          4444   4
```

CUSTOMER SUPPORT BULLETIN

CONTENTS

January 10, 1985

I. IRIS SYSTEM UPDATES

   A.   CUSTOMER SUPPORT NEWS - NONE

   B.   SOFTWARE CHANGE ORDERS FOR R8.2C1 - NONE

   C.   SOFTWARE CHANGE ORDERS FOR R7.5

        1.   Problem: STYLUS discsub number 104 shares code with
             STYLUS discsub 105 and the N bit is not set.

II. DOCUMENTATION UPDATES

   A.   PUBLICATIONS BULLETIN

III. APPLICATIONS SUPPORT BULLETIN

IV. TECH SUPPORT BULLETIN

V. TRAINING BULLETIN

R7.5 SCOs

January 10, 1985

Point 4 Data Corporation

```
+--- P4DC production manager only ---+    Patch #: DSB375-07
|                                    |
| Status    _____                |    Product (from JCL name): STYLUS
| Production System                  |
| Update by_____  Date__/__/__  |    File to be patched: DISCSUBS
|                                    |
| SCO #     _____  Date__/__/__  |    Asm Date: 03-Dec-81  Release#: 7.5&A
| Master File                        |
| Update by_____  Date__/__/__  |    Update Date: 06-Dec-84  By: LLMA
| Master File                        |
| Name      _____  |    Update Type: PATCH
+------------------------------------+
```

Problem: STYLUS discsub number 104 shares code with STYLUS discsub 105 and the

N bit is not set.

Special Instructions: Do NOT make discsub number 104 memory resident.

If discsub 105 is memory resident discsub 104 will be memory resident also.

Systems Requiring Patch: ALL

Location (Octal)	New Contents (Octal a/o Symbolic)	Comments (Describe Solution)	Old Contents
012002	60104	;SET INCLUDED BIT	040104