		-
PAGE	NΟ	Т.

DATA GENERAL CORP.

PRODUCT NUMBER

2022

FIELD ENGINEERING SUPPORT

DESCRIPTION

4001 Chassis

ECO REVISION/HISTORY LOG

KEY NUMBER

007-000-003

		1		Eco REVISION/III				
REVI	SION				PCB ASSY NUMBER 00	5-000-040		
KEY NO.	PCB ASSY 005	В		DEACON 6		DOCUMENT		
	1	140.	ASS NO.	REASON for CHANGE	REWORK INSTRUCTION	DOC NO.	PREV REV	
0	1	N/A						
1	2	237	3	Add part and update parts list.		-		
2	3	N/A			· · · · · · · · · · · · · · · · · · ·			
3	4	N/A						
4	5	N/A				-		
5	6	588	3	To clarify criteria for inspection of PCB conductors.		1		
6	7	979	3	To clarify 108/118/130 docu- ment series.		 - -		
7	8	2799	2	Handle improvement		† 		
8	9	2785	3	Tolerance on guide changed when installing PCB.		- - -		
9	10	30272	. 3	Riveting fixtures in Fab Shop makes added expense of slotted holes unnecessary.				
			•					
			•					