

PARTS LIST  
ZETACO

FOR: EXTERNAL A CABLE ASSEMBLY

ASSEMBLY #: 300-013-00  
REV. LEVEL: F

ITEM	QTY	PART #	GENERIC DESCRIP.	DESCRIPTION	REFERENCE
----	----	-----	-----	-----	-----
1	1	026-023-00	CONN M	AMP 204509-3 D-SUB	
2	60	028-009-00	CONN PIN M	AMP 66718-5	
3	1	030-039-00	CONN HDW	AMP 747098-7 HOOD	
5	1	030-018-00	CONN HDW	2-745129-3 FERRULE IN	
6	1	030-020-00	CONN HDW	1-745130-1 FERRULE OUT	
7	1	020-016-00	CABLE	SHLD 30PR 60CNDCT 28AWG	
8	1	025-041-00	CONN F	3M 3334-6060 60S	
9	1	030-034-00	CONN HDW	3M 3490-5 PULL TAB	
10	2	099-011-00	LABEL	SLSH-20375 BRADY RND CBL	
11	1	018-020-00	CABLE MATL	1/2" THERMOFIT	
12	1	093-006-00	WIRE TERM	SPADE LUG 12-10	
13	1	018-023-00	CABLE MATL	1/8" THERMOFIT	

End of List

No Control Documents on file for this list

WIRE LIST  
ZETACO

FOR: EXTERNAL A CABLE ASSEMBLY

ASSEMBLY #: 300-013-00  
REV. LEVEL: F

WIRE NO.	GA.	COLOR	ORIGIN CONN.	PIN#	TERM METHOD	DESTINATION CONN.	PIN#	TERM METHOD	SIGNAL NAME/ REMARKS
1	28	BRN	P1		MASS	P2	1	2	TW PR
2	28	BLK	P1		MASS	P2	2	2	
3	28	RED	P1		MASS	P2	3	2	TW PR
4	28	BLK	P1		MASS	P2	4	2	
5	28	ORG	P1		MASS	P2	5	2	TW PR
6	28	BLK	P1		MASS	P2	6	2	
7	28	YEL	P1		MASS	P2	7	2	TW PR
8	28	BLK	P1		MASS	P2	8	2	
9	28	GRN	P1		MASS	P2	9	2	TW PR
10	28	BLK	P1		MASS	P2	10	2	
11	28	BLU	P1		MASS	P2	11	2	TW PR
12	28	BLK	P1		MASS	P2	12	2	
13	28	VIO	P1		MASS	P2	13	2	TW PR
14	28	BLK	P1		MASS	P2	14	2	
15	28	GRY	P1		MASS	P2	15	2	TW PR
16	28	BLK	P1		MASS	P2	16	2	
17	28	WHT	P1		MASS	P2	17	2	TW PR
18	28	BLK	P1		MASS	P2	18	2	
19	28	RED	P1		MASS	P2	19	2	TW PR
20	28	BRN	P1		MASS	P2	20	2	
21	28	ORG	P1		MASS	P2	21	2	TW PR
22	28	BRN	P1		MASS	P2	22	2	
23	28	YEL	P1		MASS	P2	23	2	TW PR
24	28	BRN	P1		MASS	P2	24	2	
25	28	GRN	P1		MASS	P2	25	2	TW PR
26	28	BRN	P1		MASS	P2	26	2	
27	28	BLU	P1		MASS	P2	27	2	TW PR
28	28	BRN	P1		MASS	P2	28	2	
29	28	VIO	P1		MASS	P2	29	2	TW PR
30	28	BRN	P1		MASS	P2	30	2	

WIRE LIST  
ZETACO

FOR: EXTERNAL A CABLE ASSEMBLY

ASSEMBLY #: 300-013-00  
REV. LEVEL: F

WIRE NO.	GA.	COLOR	ORIGIN CONN.	PIN#	TERM METHOD	DESTINATION CONN.	PIN#	TERM METHOD	SIGNAL NAME/REMARKS
31	28	GRY	P1		MASS	P2	31	2	TW PR
32	28	BRN	P1		MASS	P2	32	2	
33	28	WHT	P1		MASS	P2	33	2	TW PR
34	28	BRN	P1		MASS	P2	34	2	
35	28	ORG	P1		MASS	P2	35	2	TW PR
36	28	RED	P1		MASS	P2	36	2	
37	28	YEL	P1		MASS	P2	37	2	TW PR
38	28	RED	P1		MASS	P2	38	2	
39	28	GRN	P1		MASS	P2	39	2	TW PR
40	28	RED	P1		MASS	P2	40	2	
41	28	BLU	P1		MASS	P2	41	2	TW PR
42	28	RED	P1		MASS	P2	42	2	
43	28	VIO	P1		MASS	P2	43	2	TW PR
44	28	RED	P1		MASS	P2	44	2	
45	28	GRY	P1		MASS	P2	45	2	TW PR
46	28	RED	P1		MASS	P2	46	2	
47	28	WHT	P1		MASS	P2	47	2	TW PR
48	28	RED	P1		MASS	P2	48	2	
49	28	YEL	P1		MASS	P2	49	2	TW PR
50	28	ORG	P1		MASS	P2	50	2	
51	28	GRN	P1		MASS	P2	51	2	TW PR
52	28	ORG	P1		MASS	P2	52	2	
53	28	BLU	P1		MASS	P2	53	2	TW PR
54	28	ORG	P1		MASS	P2	54	2	
55	28	VIO	P1		MASS	P2	55	2	TW PR
56	28	ORG	P1		MASS	P2	56	2	
57	28	GRY	P1		MASS	P2	57	2	TW PR
58	28	ORG	P1		MASS	P2	58	2	
59	28	WHT	P1		MASS	P2	59	2	TW PR
60	28	ORG	P1		MASS	P2	60	2	